

## **SERVICE BULLETIN APM-023**

### **Product: Advanced Power Monitor**

**Subject: Firmware 2.84 Release**

**Date: 20<sup>th</sup> April 2019**

#### Description

This Service Bulletin announces the release of baseline 2.84 firmware for the Advanced Power Monitor (APM) series products.

The version 2.84 firmware update file ("FFP") is available for download from the RFI website <http://www.rfi-motorola.com/AdvancedPowerMonitors.aspx>, and may be flashed into existing APM models by following the *Maintenance – Firmware Update* process in the Graphical User Interface (GUI) or User Manual.

#### Product Enhancement

This version 2.84 firmware supports the use of an updated divider device that is now used in the manufacture of the APM products. No new APM features are introduced in this firmware release. This version 2.84 is fully compatible with APM units built using the older divider device.

#### Upgrading to Firmware 2.84

**Note:** Please read all Service Bulletins published from the release of the firmware currently operating in your APM prior to commencing an upgrade to this version 2.84 firmware. Upgrades may require a transition through an intermediate firmware version on the way to reaching this version - or may have other implications for your APM.

The required intermediate firmware version transitions are;

- Firmware below version 2.0 must transition through version 2.0 or 2.05 prior to attempting an update to 2.1 or above.
- Firmware below 2.60 must transition through version 2.60 prior to attempting an update to 2.70 or above.

#### Cost Impact

Firmware version 2.84 is available to RFI customers at no charge.